

## State Water Resources Control Board

June 7, 2016

(Via email and Certified Mail)

**CERTIFIED MAIL**

**NO. 7015 1520 0001 8019 6514**

Ms. Pamela Carney  
Transportation Supervisor  
Shasta Tehama Trinity Joint Community College  
P.O. Box 496006  
Redding, California 96049-6006  
[pcarney@shastacollege.edu](mailto:pcarney@shastacollege.edu)

**SUBJECT: NOTICE OF VIOLATION; UNDERGROUND STORAGE TANK SYSTEMS  
LOCATED AT SHASTA TEHAMA TRINITY JOINT COMMUNITY COLLEGE,  
11555 OLD OREGON TRAIL, REDDING**

Dear Ms. Carney:

As part of an initiative by the State Water Resources Control Board (State Water Board) to ensure compliance at government-owned and/or operated underground storage tank (UST) facilities in California, the State Water Board staff inspected the USTs at your facility on May 25, 2016, pursuant to authority under Health and Safety Code (H&SC), chapter 6.7, section 25289.

The State Water Board has identified the following violations pursuant to H&SC, chapter 6.7, and title 23, California Code of Regulations (CCR), chapter 16:

No.	Violation	Tank	Start Date	Stop Date	Regulation
1	<b>Failure to Maintain Monitoring or Testing Records On-site</b> – The 2015 monitoring certification and line leak detector test results were not available at the time of inspection.	All	May 25, 2016	Ongoing	H&SC 25293; 23 CCR 2712(b)
2	<b>Failure to Tag Monitoring Equipment</b> – The automatic tank gauge did not have a monitoring certification tag affixed.	All Waste Oil	May 25, 2016	Ongoing	23 CCR 2638(f)
3	<b>Failure to Monitor Product Piping</b> – Several sump sensors were raised and others were not placed in the lowest point in the sump.	Diesel and all Waste Oil	May 25, 2016	Ongoing	23 CCR 2630(d)
4	<b>Failure to Maintain Facility and Tank Information</b> – The CERS tank information form must list a form of corrosion protection and fill components.	Unleaded	May 25, 2016	Ongoing	23 CCR 2711(a)

FELICIA MARCUS, CHAIR | THOMAS HOWARD, EXECUTIVE DIRECTOR

No.	Violation	Tank	Start Date	Stop Date	Regulation
5	<b>Failure to Maintain Financial Responsibility</b> – A Certificate of Financial Responsibility is required for this facility. The insurance policy observed is expired.	All	September 20, 2014	Ongoing	H&SC 25292.2; 23 CCR 2711(a)(11)

**You are directed to correct the ongoing violations and submit compliance documentation to the State Water Board and Shasta County Environmental Health Division within sixty (60) days from the date of this letter. Have your Designated Operator make specific notations in the next monthly designated operator report indicating the ongoing violations have been corrected. The monthly designated operator report and any associated photos must be submitted as proof of compliance.**

Please send all compliance documentation to the following:

**State Water Board**

Mr. Thomas Henderson  
UST Enforcement Unit  
Office of Enforcement  
State Water Resources Control Board  
1001 I Street, 16<sup>th</sup> Floor  
Sacramento, California 95814  
[tom.henderson@waterboards.ca.gov](mailto:tom.henderson@waterboards.ca.gov)

**Local CUPA**

Mr. Kevin Westlake  
Environmental Health Specialist  
Shasta County Environmental Health Division  
1855 Placer Street, Suite 201  
Redding California, 96001  
[kwestlake@co.shasta.ca.us](mailto:kwestlake@co.shasta.ca.us)

Pursuant to Health and Safety Code, chapter 6.7, section 25299, the owner and operator of the tank(s) are liable for a penalty of \$500 to \$5,000 per tank, per day of violation. These penalties will continue to accrue until the violations have been corrected.

If you have any questions, please contact me at (916) 341-5551, or by email at [amantha.henkel@waterboards.ca.gov](mailto:amantha.henkel@waterboards.ca.gov).

Sincerely,



Amantha Henkel  
Senior Environmental Scientist  
UST Enforcement Unit  
**Office of Enforcement**

cc: (via email only)

Mr. Kevin Westlake  
Shasta County Environmental Health Division  
[kwestlake@co.shasta.ca.us](mailto:kwestlake@co.shasta.ca.us)